

BERNIE








Diagram illustrating assembly instructions and safety warnings:

- Warning 1:** A warning triangle with an exclamation mark is shown next to a box containing an L-shaped metal bracket and a crossed-out power drill icon, indicating that a power drill should not be used for this step.
- Warning 2:** A second warning triangle with an exclamation mark is shown next to a box containing a rectangular block being placed on a surface and a crossed-out icon of a block being pushed down, indicating that the block should be placed gently.
- Time:** A clock icon is shown next to the text "20'", indicating a 20-minute assembly time.
- Personnel:** A person icon is shown next to the number "1", indicating that one person is required for assembly.


A



B




A




x 1

B



x 1

C



M8
x
10


x 3

D



x 3

E



x 1

1

